



VIEW OF SUBJECT PROPERTY FROM UPPER LAWN



EXISTING GRANITE STAIRCASE



EXISTING RETAINING WALL WITH ROTTEN BALCONY ABOVE



VIEW TO SOUTH FROM PROPOSED TERRACE



VIEW FROM SUBJECT PROPERTY TO EAST: POOL MECHANICAL EQUIPMENT AT 4769 THE HIGHWAY



EXISTING LOW GRANITE RETAINING WALL