

District of West Vancouver Development Permit No. 20-007

CURRENT OWNER: MAGED SHEHATA

THIS DEVELOPMENT PERMIT APPLIES TO:

CIVIC ADDRESS: 2950 ROSEBERY AVENUE

LEGAL DESCRIPTION: PID 007-504-527

LOT A BLOCKS 116 AND 117 DISTRICT LOT 556 PLAN

16392 (the 'Lands')

1. This Development Permit:

- a) imposes requirements and conditions for the development of the Lands, which are designated by the Official Community Plan as Development Permit Area to ensure that detached secondary suites meet a high quality of building and landscape design, and are compatible both with the principal dwelling on the lot, and the built form character of the local neighbourhood and subject to Guidelines BF-B 3.1 specified in the Official Community Plan;
- b) is issued subject to the Owner's compliance with all of the Bylaws of the District applicable to the Lands, except as varied or supplemented by this Permit.
- 2. The following requirements and conditions shall apply to the Lands:
 - a) Building, structures, and site development shall take place in accordance with the attached **Schedule A**.
 - b) Landscaping must adhere to **Schedule B**.
 - c) Tree protection, removal, and replacement shall take place in accordance with **Schedule C**.
- 3. Prior to commencing site work or Building Permit issuance, whichever occurs first, the Owner shall:
 - a) provide and implement a plan for traffic management during construction, to the satisfaction of the District's Manager of Land Development; and
 - b) install tree, vegetation and/or hedge protection measures as required to the satisfaction of the District's Environmental Protection Officer; and

Page: 2 DP No. 20-007

 submit a "Sediment and Erosion Control Plan" to the District's Environmental Protection Officer for approval, and the owner shall be responsible for maintaining, repairing and implementing the Sediment Control Measures.

- 4. Prior to Building Permit application and as security for the due and proper completion of the measures to protect development and landscaping set forth in Section 2 of this Development Permit (the "Tree Protection Measures"), the Owner shall:
 - (a) provide security in the amount of \$5,000.00 to the District in the form of cheque; and
 - (b) maintain the security until completion of the work, and not prior to the date on which the District Environmental Protection Officer authorizes in writing the release of the security.
- 5. In the event that the landscaping is not completed or trees retained as provided for in this Permit, the District may, at its option, enter upon, carry out and complete the landscaping or tree replacement so as to satisfy the terms of the Development Permit, and recover the costs of doing so from the security deposited, including the costs of administration and supervision.
- 6. This Development Permit lapses if the work authorized herein is not commenced within 24 months of the date this permit is issued.

THE DIRECTOR OF PLANNING AND DEVELOPMENT SERVICES APPROVED THIS DEVELOPMENT PERMIT ON July 21, 2021

Jim Balley, Director of Planning and Development Services

THE REQUIREMENTS AND CONDITIONS UPON WHICH THIS PERMIT IS ISSUED ARE ACKNOWLEDGED AND AGREED TO BY THE CURRENT OWNER. IT IS UNDERSTOOD:

- THAT OTHER PERMITS / APPROVALS MAY BE REQUIRED INCLUDING PERMITS / APPROVALS FOR BUILDING CONSTRUCTION, SOIL AND ROCK REMOVAL OR DEPOSIT, BOULEVARD WORKS, AND SUBDIVISION; AND
- THE DEVELOPMENT MUST ATTAIN REQUIREMENTS OF THE BC BUILDING CODE AND ANY VARIANCES TO THE ZONING BYLAW ARE THE RESPONSIBILITY OF THE OWNER AND MUST BE RECTIFED AT THE BUILDING PERMIT STAGE.

Page: 3 DP No. 20-007

FOR THE PURPOSES OF SECTION 6, THIS PERMIT IS ISSUED ON July 21, 2021.

Schedules:


A – Proposed Development Plans, prepared by Design Marque Consulting Ltd., date received July 19, 2021


B – Landscape Plan, prepared by Design Marque Consulting Ltd., date received June 17, 2021


C – Arborist Report, prepared by uTree Environmental Consultants, date received April 13, 2021


Schedule A to DP 20-007












COPYRIGHT RESERVED

These design and drawings, at all times, remain the exclusive property of the designer DESIGN MARQUE and cannot be used or reproduced without written

Written dimension shall have precedence over scaled dimensions. Contractors/Builders shall verify and be responsible for all dimensions and conditions on the job-site. Designer shall be informed of any variations from the dimensions and conditions shown on the drawings.



No.	Date	Revision
1		

3		
2	Nov 25 2019	Issued for D.P.
1	Nov 06 2019	Issued for Owner Approval
No.	Date	Issues:

DESIGN MARQUE

PHONE: 604.925.4101 CELL: 604.788.5555 FAX: 604.925.4103 E-MAIL: marque@designmarque.com WWW.designmarque.com

1765 Bellevue Ave. West Vancouver, B.C. V6V 1A8

F2a DECK FLOOR (NON INSULATED)
3/4" PORCELAIN PAVERS ON PEDESTAL (FOR LEVELING)

9 1/2" TJI FLR. JOISTS @ 16" O.C. AS PER STRUCTURAL

1/2" IRONWOOD SOFFIT W/ CONTINUOUS VENTING

3-PLY TORCH-ON MEMBRANE

8" CONCRETE WALL

1/2" GYPSUM BOARD

BUILDING WRAP

2X10" ROOF RAFTERS @ 16"AS PER ENGINEERING DWGS. 1 1/2" PURLINS (1% SLOPED TO DRAIN MINIMUM)

5/8" T&G PLYWOOD SHEATHING

W1a BELOW GRADE WALL (insulated)
2 COATS OF BITUMOUS DAMPROOFING

2"x4" WOOD STUDS @ 16" O.C. w/ R-28 BATT

W2 TYP.ABOVE GRADE WALL (insulated)
STUCCO OR NATURAL STONE VENEER

1.5" XPS RIGID FOAM INSULATION R-7.5

W2a TYP.ABOVE GRADE WALL (insulated)
STUCCO OR NATURAL STONE VENEER

VENTED AIR SPACE (RAINSCREEN)

1/2" EXT. GRADE PLYWOOD

6 mil POLY. VAPOUR BARRIER

W3 TYP. INTERIOR WALL (2x4)

2"x4" WOOD STUDS @ 16" O.C.

ACOUSTIC BATT INSULATION (OPTIONAL)

1/2" GYPSUM BOARD

1/2" GYPSUM BOARD

1/2" GYPSUM BOARD

2"x6" WOOD STUDS @ 16" O.C. W/ R-24 HD BATT

2"x6" WOOD STUDS @ 16" O.C. W/ R-24 HD BATT

VENTED AIR SPACE (RAINSCREEN)

1/2" EXT. GRADE PLYWOOD

6 mil POLY. VAPOUR BARRIER

1/2" GYPSUM BOARD

BUILDING WRAP

Maged Shehata **Detached Secondary**

2950 Rosebery Ave. West Vancouver, B.C.

Drawing Title:

WEST & NORTH ELEVATIONS

Checked: October 2019

Drawing No: Plot Size: 36" x 24"

F2 WOOD FLOOR (HEATED)
FLOOR FINISH 1 1/2" LIGHTWEIGHT CONC. TOPPING RADIANT HEATING PIPES ON WIRE MESH 5/8" T&G PLYWOOD SUBFLOOR 11 7/8" TJI FLR. JOISTS @ 16" 1/2" GYPSUM BOARD

CONSTRUCTION ASSEMBLIES

15 LB. FELT UNDERLAYMENT

R1a ROOF TRUSS SYSTEM
METAL STANDING SEAM ROOF

15 LB. FELT UNDERLAYMENT

15 LB. FELT UNDERLAYMENT

R-50 BATT INSULATION

6 mil VAPOUR BARRIER

1/2" GYPSUM BOARD

4" CONC. FLOOR SLAB

R12 RIGID INSULATION

4" CONC. FLOOR SLAB

R12 RIGID INSULATION

SOLID BEARING

5" (MIN.) COMPACTED GRAVEL

SOLID BEARING

5" (MIN.) COMPACTED GRAVEL

R1 FLAT ROOF (NON INSULATED)
2 PLY TORCH ON MEMBRANE

1/2" PLYWOOD SHEATHING W/ H-CLIPS

WOOD SOFFIT W/ CONTINUOUS VENTING

1/2" PLYWOOD SHEATHING W/ H-CLIPS

ROOF TRUSSES AS PER ENGINEERING DWGS.

R1b ROOF TRUSS SYSTEM (NON INSULATED)
METAL STANDING SEAM ROOF

1/2" PLYWOOD SHEATHING W/ H-CLIPS

ROOF TRUSSES AS PER ENGINEERING DWGS.

WOOD SOFFIT W/ CONTINUOUS VENTING

F1a CONC. FLOOR SLAB (LIVING AREAS) FLOOR FINISH

RADIANT HEATING PIPES ON WIRE MESH

F1b CONC. FLOOR SLAB (LIVING AREAS)
SEALED CONCRETE FINISH

RADIANT HEATING PIPES ON WIRE MESH


6 mil VAPOUR BARRIER (MIN. 4" LAP @ JOINTS)


6 mil VAPOUR BARRIER (MIN. 4" LAP @ JOINTS)

1 1/2" LIGHTWEIGHT CONC. TOPPING

ALL ROOF, FLOOR AND WALL ASSEMBLIES; WINDOWS, GLASS DOORS AND DOORS TO COMPLY WITH 9.36 BCBC 2018 ENERGY EFFICIENCY

PAINT





District of West Vancouver Community Planning and Development



Arborist Report

March 25, 2021

Re: 2950 Rosebery Avenue

Introduction

The owner is proposing development of the property with a new Coach House. An Arborists assessment of the trees is required to ensure tree management for the project complies with the District of West Vancouver's "Tree Bylaw". This report has been written in support of the application.

Existing Condition

The property is large (7353.65 m²) and has a moderate slope from north to south. The property was initially developed in 1932, then updated in 2006. The site has a single family dwelling, an indoor swimming pool and an accessory building. The accessory building has been demolished but it's foundation remains.

Cedar trees form a screen allong the east, west property boundaries and on the boulevard. Most of the cedars are off-site. On-site there are a mixture of native cedar and ornimental decedouous trees.

In anticipation of development, minimal effort has dedicated to the mainanance of the existing landscape. Generally both the hard and soft landscaping are in fair to poor condition.

Inspection

A site inspection was made by uTree Environmental Consultants, May 13, 2020. The assessment was limited to a ground based visual inspection. No invasive techniques were used.

Discussion and Recommendations

The property is large; the proposed development is confined to the south-west corner of the site. Eight trees on-site are proposed to be removed; the largest being 36.6cm in diametre. These trees are not significant and are not protected by the "Tree Bylaw"; a tree permit is not required.

Table 1 – On-site, south-west corner of the property.

Tree#	Species	Diametre	Tree	General Condition - Recommendations'
		cm	Protection	
			CRZ	
1, 2,	Small	10 - 15	n/a	Repeated pruning
3,	ornamental			Fair to poor health
and	trees			Some with decay on limbs and trunk
4				See Photo 1
				Remove
5	Red Cedar	36.6	n/a	Good Health and Vigour
	Thuja plicata			Pistol grip growth form
				Remove for the new driveway
6	Pine	21.3	n/a	Poor condition
	Pinus spp.			Remove for the new driveway
7	Paper Birch	22.9	n/a	Fair condition
	Betula			Repeated pruning
	papyrifera			Decay in the stem and branch unions
				Remove for the new driveway
8	Vine maple	33.5	n/a	Good Health and Vigour
	Acer			Some included bark at the base
	circinatum			Tree is too close to the work area.
				Remove for the new Coach House
	Vine maple	30.5	2.1m	Good Health and Vigour
9	Acer			Some included bark at the base
	circinatum			See Photo #2
				Tree protection required

No off-site trees are proposed to be removed. The existing screen created by the mature trees outside the west property boundary will be retained. There are 5 trees that are near the work zone, labeled A to E (Table 2 and Tree Management Plan). Tree protection and monitoring during excavation is proposed to ensure the trees health is not impacted by the development.

Table 2 – Off-site, outside west property line

Tree#	Species	Diametre	Critical	General Condition - Recommendations
		cm	Root	
			Zone	
Α	Red Cedar	54.9	3.3	Located on neighbours property
	Thuja plicata			Good Health and Vigour
				Tree has been topped at least two time – Multi-
				leader
				Tree protection is required.
В	Red Cedar	54.9	3.3	Located on neighbours property
	Thuja plicata			Good Health and Vigour
				Trunk - sweep from the base
				Tree has been topped at least two time – Multi-
				leader
				Tree protection and monitoring during
				excavation is required.
С	Red Cedar	73.2	4.5	Located on neighbours property
	Thuja plicata			Poor Health and Vigour
				Tree has been topped at least two time – Multi-
				leader
				Tree protection and monitoring during
				excavation is required.
D	Western	61.0	3.6	Located on neighbours property
	Hemlock			Very Poor Health and Vigour
	Tsuga			Tree has been topped – Multi-leader
	heterophylla			Tree protection and monitoring during
				excavation is required.

E	Western	75cm	4.5	Located on neighbours property
	Hemlock			Fair Health and Vigour
	Tsuga			Neighbouring tree has been removed, deadwood
	heterophylla			on the north side is exposed.
				Ivy infestation
				Tree protection is required.

Tree Protection

Tree protection measures can be seen in the attached "Tree Management Plan".

To comply with Schedule A of the 'Tree Bylaw', excavation and installation of a hedge on the west side of the development, near trees B, C and D, must be done under the direction of a certified Arborist. The Arborist must:

- ensure minimal damage to existing roots
- be on-site to monitor excavation
- be on-site to monitor installation of hedge
- root prune exposed roots at the edge of the excavation
- ensure tree protection fencing is in place after the excavation is complete.

Limitations

It is my policy to attach the following clause regarding limitations. We do this to ensure that the client is aware of what is technically and professionally realistic in retaining trees.

The assessment of the trees presented in this report has been made using accepted arboricultural techniques. These include a visual examination of all the above ground parts of the tree for structural defects, scars, external indications of decay such as fungal fruiting bodies, evidence of attack by insects, discoloured foliage, the condition of any visible root structures, the degree and direction of lean (if any), the general condition of the trees and the surrounding site, and the proximity of property and people. Except where specifically noted, the trees were not cored, probed or climbed and there was no detailed inspection of the root crowns involving excavations.

Notwithstanding the recommendations and conclusions made in this report, it must be recognized that trees are living organisms, and their health and vigour constantly change over time. They are not immune to changes in site conditions or seasonal variations in the weather conditions. While reasonable efforts have been made to ensure that the subject trees are healthy, no guarantees are offered, or implied, that these trees or any of their parts will remain standing. It is both professionally and practically impossible to predict with absolute certainty the behaviour of any single tree or its component parts under all circumstances. Inevitably, a standing tree will always pose some level of risk.

Most trees have the potential for failure under adverse weather conditions, and the risk can only be eliminated if the tree is removed. Although every effort has been made to ensure that this assessment is reasonably accurate, the trees should be re-assessed periodically. The assessment presented in this report is valid at the time of inspection.

Closure

We trust this report provides the information you currently require. If you have any questions regarding this report, please feel free to contact me.

Sincerely,

Andrew Vander Helm, RPBio, ISA Arborist

andellel

Appendix A – Site Photos



Photo 1 - Tree (3)

Photo 3 - (Tree D) Topped Hemlock

Photo 2 - Tree (9) To be retained



Photo 4 – (Tree C) Topped Cedar



Photo 5 – (Tree A) Topped Cedar

